

Heat loss shown in Thermal Imaging over Alter Windows



IR000058.IS2

10/14/2019 8:24:58 AM

26Dec19 – When this area was opened up, we found large gaps around the window frames and no Insulation above windows. The gaps were filled with spray foam insulation. New Fiberglass batt insulation was installed above the windows, then covered with rigid foam insulation fitted tightly around the roof purlins.